

DATE SUBMITTED 11/25/19
 SUBMITTED BY COMMUNITY SERVICES
 DATE ACTION REQUIRED 12/04/19

COUNCIL ACTION (X)
 PUBLIC HEARING REQUIRED ()
 RESOLUTION ()
 ORDINANCE 1ST READING ()
 ORDINANCE 2ND READING ()
 CITY CLERK'S INITIALS (Signature)

**IMPERIAL CITY COUNCIL
 AGENDA ITEM**

SUBJECT: DISCUSSION/ACTION: REMOVAL AND REPLACEMENT OF RUBBER SURFACING AT VICTORIA PARK, SKY RANCH PARK, AND SAVANNA PARK	
1. Authorization to seek bids for the removal and replacement of pour-in-place rubber surfacing at Savanna Park; 2. Authorization to seek bids for the removal and replacement of pour-in-place rubber surfacing at Sky Ranch Park; 3. Authorization to seek bids for the removal and replacement of pour-in-place rubber surfacing at Victoria Park.	
DEPARTMENT INVOLVED: <u>COMMUNITY SERVICES</u>	
BACKGROUND/SUMMARY: The pour-in-place rubber surfacing at Savanna, Sky Ranch, and Victoria Parks are in poor condition and have exceeded life expectancy. An inspection of all 3 parks (Savanna, Sky Ranch, Victoria) confirmed the need of complete removal and replacement of the existing rubber surfacing due to weathering, severe granulation, spider cracks and top layer peeling. Please see report for reference.	
FISCAL IMPACT: Savanna Park – Estimated cost of \$123,600 – Community Facilities District Sky Ranch Park – Estimated cost of \$106,000 – Lighting and Landscape District Victoria Park – Estimated cost of \$24,000 – Community Facilities District	FINANCE INITIALS _____
STAFF RECOMMENDATION: It is the department's recommendation for Council to authorize the seeking of bids for Removal and Replacement of existing Rubber Surfacing at Victoria Park, Sky Ranch Park, and Savanna Park.	DEPT. INITIALS <u>(Signature)</u>
MANAGER'S RECOMMENDATION:	CITY MANAGER'S INITIALS <u>(Signature)</u>
MOTION: SECONDED: _____ APPROVED () REJECTED () AYES: _____ DISAPPROVED () DEFERRED () NAYES: _____	

SAVANNA PARK



Size:

6,990 SF

Damage:

Weathering, severe granulation, spider cracks, and peeling top layer

Recommendation:

Remove and replace existing rubber surfacing

Approx. Cost:

123,600.00

SKY RANCH



Size:

1,040 SF

Damage:

Weathering, severe granulation, spider cracks, and peeling top layer

Recommendation:

Remove and replace existing rubber surfacing

Approx. Cost:

\$24,000.00

VICTORIA PARK



Size:

6,110 SF

Damage:

Weathering, severe granulation, spider cracks, and peeling top layer

Recommendation:

Remove and replace existing rubber surfacing

Approx. Cost:

\$106,000.00